The Assistant Engineer (QC) Quality Control Lab, DUSIB Vikas Kutir, ITO, New Delhi

0 9 AUG 2018

Part I D-21 /AEXII/C-7/DUSIB/2018 2018-19 No. Sub: Testing of Bricks/Bricks Tiles for Water Absorption/Efflorescence.

Date: 09 8/18

2. Sub Head:-Providing & laying RMC pavement & drainage system in lanes at JJC Rajpura Gur Ki Mandi, (AC-18 Model Town) PID No-0000010022)

Acceptance No. WI/6031/AL-06/EEC-7/2018-19/D-483

DATE:-17-05-2018

3. Name of Circle/Division: Circle-VII, C-7 Name of Junior Engineer 4. Sh. Vikas kumar 5. Name of Assistant Engineer: Sh. Tarun Gaur Name of Executive Engineer: 6. Sh . Rajindra Bansal 7. Name of Contractor/Agency: M/s. A.D Construction Co. 8. Name of Officer collection sample:

Sh. Tarun Gaur 9. Date of collection/Date of filling frog:61841.8....

10. Date of Testing:

11. Identification Mark: 12. Class designation:

13. No. of specimen sent for testing: 7.5 10

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample (S) marked has/have been taken in my presenge represent. 3000. quantity of work/supply made at site/store.

Signature of JE In-charge of work

Signature of Contractor

taking sample (EE/AE)

Part II

TEST REPORT

Date: 03/09/18

No. SE (QC)/AE (Lab)/2018/D- 751

Test No. 588

Date 9-8-18

Date of Receipt 3 9 8/18 Date of Testing ! 9/8/18

(A) WATER ABSORPTION

Day of Testing upto 14 -8, 13

S.	Dry Wt. (gms)	Wet Wt.(gms)	136	S apro	14 -01 10
No.		wet we(gins)	Water Absorbed (gms)	%age water Absorbed	Average absorption
1.	2665	3009	344	12.91	water
3.	2678	3069	326	11.88	18 09 7.
5.	2978	3128 3071	350	12.40	ACCEPTABLE
(B)+	FFLORESCEN	CE		12.67	

ACCEPTABLE

Dt. of testing upto: 30/8/18

NUTSLIGHT / MODERATE / HEAVY

Only testing has been conducted in this laboratory, the samples have been collected. cured, and handed over by the field staff of the concerned division.

Copy to:

EE/C-7

Assistant Engineer (QC) 1200. 30 DUSIB, Vikas Kutir, ITO

2. %