ikas Kuteer.ITO,New Delhi.	
Part I No. 17 AE-II 6-2 D vsi B L.No.:-WF/4766/21/AE-III/C-2/2017-18/D-812 Date Name of work: Imp. of SC/ST/ OBC Minorities Bastic	ted:-28.03.2018
. Name of work, hip, of SC/S1/ OBC villiornes basic	1
Sub Head:- Construction of Julaha Chaupal (3-Storeyed)	at Village Mundka, AC-8,
Mundka.(Project ID -10099) Details from where sample is collected:	From Site
Name of Circle / Division:	C-2
Name of Junior Engineer:	Sh. Ravinder Kumar
. Name of Assistant Engineer:	Sh. P.S. Johar
Name of Executive Engineer:	Sh. S.C. Sharmer Kamal Singh
7. Name of Contractor / Agency:	M/S Vashishth Associates.
Name of Officer Collecting Sample:	Sh.P.S. Johar
9. Date of collection: 10. Quantity of sample sent for testing: Specimen relating to work mentioned above that the sample (s) marked	ken in my presence which represent
Signature of J.E. Signature of Contractor In charge of work	Signature of Officer 2 Taking sample(EB/AE)

TEST REPORT

No.SE(QC)/AE(Lab)/2018/D- 2200 Test No...1842 Date 25:219

Date 01 03 19 Date of Receipt..... 25.2:19.....

(A)SLIT CONTENT Height of slit content

Height of sand %age of slit content not asked for =

(B) GRADING

S. No	Sieve mm	Weight retained in (Gms.)	% Weight retained	Cumulative %age retained	%age passing	Regd. %age passing as per specification
1	10.0	agm	0.00	7:00	100,00	100
2	4.75	00	0100	0:05	12.00	90-100
3	2.36	مه	0.00	0.00	lanco	85-100
4	1.18	L (L v	f. 60	6.8	91.20	75-100
5	600micron	1020	20140	29.20	4.80	60-79
6	300micron	264 v	22.80	82 0	18.00	12-40
7	150micron	189	11.60	93.60	6.40	0-10
8	Pan	320	64400	المه وما	0.00	. ACCEPTABL

and handed over by the field staff of the division.

(OPY To:

(EE/c-2) Only testing has been conducted in this laboratory, the sample have been collected, cured

20/0

Assistant Engineer (QC) Lab. Delhibalyskas Kallestolli Qv Son. o' N.C.L. of Dahl

ITO, New Delhi-62