R-No: 3739.

19 MAR 2020

To

The Assistant Engineer (QC)
Quality Control Lab., DUSIB
Vikas Kutir, ITO, New Delhi

Part I

Dispatch No AE-II/C9/DUSIB/2020/D-30 Date : 18/3/2020

Sub: Testing of Bricks/Brick tiles for Compressive Strength/Dimension.

A. L. No. 54 /E.E.D.C-9/DUSIB/2016-17/D- 55 *Dated:* 11/03/2020

Name of work:- C/o JSC Bays use. (Capital).

Sub Head: Construction of Platform for 30 seater, Pay & Sub JSC at Basti (S) Harijan Camp Mandawali near Dispensary & Construction of Platform for M.T.V at Krishan Kunj

1. Details from where sample is collected — *from site*
2. Name of Circle/Division — 3/C-9
3. Name of Executive Engineer — *Sh.P.K. Singh*
4. Name of Assistant Engineer — Maharaj Pal
5. Name of Junior Engineer — Veer Pal Meena
6. Name of Contractor/Agency — M/s Maheshwar Singh
7. Name of Officer collecting sample — Maharaj Pal
8. Date of collection: — 18/03/2020
9. Date of Testing — 19/03/2020
10. Quantity of sample sent for testing: — 5 NOS.
11. Identification Mark: —
12. Class designation: — 7.5
13. No. of specimen sent for testing: — 2 NO

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/ samples marked (A) has/have been taken in my presence which represent 20000 quantity of works/supply made at site/store.

Signature of AE Incharge of work — Signature of Contractor — Signature of Officer taking sample (EE/AE)

Part II **TEST REPORT**

No. SE (QC)/AE (Lab.)/2019-20/D- 4268 Date: 19/3/2020

Test No. 3739 Date: 19/03/2020

Date of Receipt: 19/3/2020

Date of Testing: 19/3/2020

(A) COMPRESSIVE STRENGTH MAIN

S. No	Dimensions Length (cms)	Width (cms)	Area (sq.cm)	Maximum Strength. Failure (T)	Compressive Strength Failure (kg/sq.cm)	Av. Comp. Strength. Kg/sq.cm
1.	22.10	11.00	243.10	20.07	82.27	ACCEPTABLE
2.	22.30	11.00	245.30	23.07	93.77	
3.	22.40	11.10	248.64	20.07	80.44	80.03
4.	21.90	10.60	232.14	18.07	77.54	kg/sq.cm
5.	22.00	11.00	242.00	16.07	66.12	

Tested in my presence

Required Strength as per IS

(B) DIMENSION TEST FOR 20 BRICKS

1. Length :
2. ~~Width~~ : Not asked for
3. Height :

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

19/3/2020

Assistant Engineer (QC-Lab)
DUSIB, Vikas Kutir, ITO
Assistant Engineer (QC)
Delhi Urban Shelter Improvement Board
Govt. of N.C.T. of Delhi
ITO, New Delhi-02

Copy to:-

1. EE/C-9
2. dc