The Assistant Engineer(QC) Quality Control Lab., DUSIB

RNO. 1287 RECEIVED 1 1 SEP 2017

	Vikas Kutir, ITO, 1	New Delh	i	116	CEIVED V. CE. LO.	
Part I						
Dispatch No AET/C-12/DUSIS/2017-18/5-156 Date: 31.8.1)						
Sub: Testing of CC cubes of mix Free for 28 days Compressive Strength.						
AL No.57/WK/7205(136)/EEC-12/DUSIB/2016-17 /D- 158 dated 25.02.2017						
NOW: SC/ST Basti fund.						
SH: Repairing/restoration of roads, providing and laying cement concrete Pavement in lanes,						
construction of SW drain in left out lanes/road in block-A at SRS Bawana. (Project ID						
000007111).						
1 Details from where sample is collected				sile.		
2 Name of Circle/Division				Circle-4/C-12		
3 Name of Junior Engineer						
4 Name of Assistant Engineer				Rakesh Kumar		
5 Name of Executive Engineer				Sh. Kamal Singh		
6 Name of Contractor/Agency				M/S Kundu Nirman		
7 Name of Officer collecting sample				Rakesh Kumar/Kamal Singh		
8 Date of collection:				31-8-17		
9 Date of testing:10 Required strength:				Is per your		
11 No. of specimen sent for testing:				03		
12 Size of specimen:			testing.	15X15X15 cm		
13 Mark of specimen:				it be		
15 Wank of specimen.						
Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/						
samples markedhas/have been taken in my presence which represent-4-2-quantity						
of works/supply made at site/store.						
	or works/suppry in	auc ai sin	distore.	-// 1	1 -	
	Ter				1 Rue	
Signature of Signature of			Signature of (
In charge of work			Signature of	taking sample (EE/AE)		
turing sumple (EE/TE)						
Part II TEST REPORT						
No. SE(QC)/AE(Lab.)/2017-18/D- 1495 Date: 04/09/17						
Test No. 1287 Date: [9.17						
Date of Receipt: 01/9/2017						
		,				
Date of testing: Oncrete Mix: Days test: 29 days						
S. No	Wt. of specimen	Area in		ive Strength	Average Strength Remarks	1
5.110	in gms	sq.cm.	Load	Comp. strength	(Kg./sq.cm)	
	III GIIIS	sq.om.	(Tonnes)	(Kg./sq.cm)	(ing., sq.cm)	
1.	8622 Aug	225	62.07			
	8622 gm	3		275.56		
2.	8654 "	332	P02.149	286.67	285.93	
	0	m	66,507	295.56	rylunz E May	
3.	85940		0-3-1	13 -		
Tostad	in my presence				Accordin	

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

120

Assistant Engineer (QC-Lab) PISTE Vileas (Rutit, ITO Peint Urban Smiller Improvement Board Sovi. of N.C.T. of Belhi

ITC. New Delhi-As

Copy to:-