The Assistant Engineer (QC) Quality Control Lab DUSIB Vikas kutir ITO New Delhi

Dispatch No: 03 AETH EECY DUSIB- Date 22/8/17

Sub: Testing Bricks for Water Absorption / efflorescence.

W.O.NO: AL-05/ EEC-4/DUSIB/2016-17

1. . Name of work: E IUS

Sub Head: Construction of SW drain and CC pavement in JJ Cluster Shaheed Sukhdev Nagar Wazirpur Industrial Area (PID:7298)-

- 2. Details from where sample as colllected
- 3. Name of circle Division
- 4. Name of Junior Engineer
- 5. Name of Assistant Engineer
- 6. Name of Executive Engineer
- 7. Name of Contractor/ Agency
- 8. Name of Officer collecting sample
- 9. Date of collection
- 10. Date of testing
- 11. Identification Mark
- 12. Class Designation
- 13. No of specimen sent for testing

Frorm the site

2/ C-4

Krishna Kumar

Sh. S.C.Gour

Sh. Anil Aggarwal

Sh.Shree Radhey Infrastucture

Sh. S.C.Gour

75

5 Nos

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/ samples marked has/have been taken in my presence which represent of work/supply made at site/store.

Signature of AE

in charge of work

(EE/AE)

Signature of Contractor

TEST REPORT

taking sample

Part -II

NO. SE(QC)/AE(Lab)/2016-17/D- 1552

Test no. 194

Date. 23.8.17

Date. 11 09 17

Date of Receipt 23 3 00

(A) WATER ABSORPTION

S.no **DRY WEIGHT** WET WEIGHT WATER %AGE -WATER (GMS) (GMS) **ABSORBED** ABSORBED. ABSORBED IN %AGE (GMS) 2950 3300 1 350 11.86 2 3239 2938 301 10-24 3 3271 2954 10.73 317 zer 5 4 11.91 3363 358 2967 3360 13.24 393

EFFLORESCENCE:

Date Of Testing upto: Efflorescence observed: All-/Slight/ Mederate/Heavy

Only testing has been conducted in this laboratory. The sample/ samples has/have been collected and handed over by the field staff of the concerned division.

Copy to-

1 EE/C-4

Assistant Engineer (QC-Lab

Assistant Engineer (QC) Nelhi Urban Sneller Improvement Board

3ov. of N.C.T. of Raihi