DELHI URBAN SHELTER IMPROVEMENT BOARD
GOVT. OF NCT OF DELHI

3415

To
The Assistant Engineer (QC)
Quality Control Lab., DUSIB
Vikas Kutir, ITO, New Delhi

RNO 361
18 JUN 2018

Part I
Dispatch No. D-133/AE(II)/C8/DUSIB/2018 Date: 18/6/18

Sub: Testing of CC cubes of mix M -25 for 7/28 days Compressive Strength.

A. T. No. 36/EE/C-8/DUSIB/17-18/D-450 Dated 23/8/17

Name of work: Imp of ... (JJC)
SH: C/o JJC Dwarka between old Secretariat DLF Dilkhad Garden (Indira Vihar Camp) Part II Roof Slab & Roof beam (G. Floor)

| | | |
|---|---|---|
| 2 | Details from where sample is collected | |
| 1 | Name of Circle/Division | C-III/C-8 |
| 3 | Name of Junior Engineer | Bal Singh |
| 4 | Name of Assistant Engineer | Sh. Rajender Singh |
| 5 | Name of Executive Engineer | Sh. K.B. Sharma |
| 7 | Name of Contractor/Agency | Sh. Rajkumar Sharma |
| | Name of Officer collecting sample | Sh. Rajender Singh AE |
| | Date of collection | 21-5-2018 |
| | Date of testing | 18-6-2018 |
| | Designed strength | M-25 |
| | No. of specimen sent for testing | Three |
| | Size of specimen | 15x15x15 cm |
| 2 | Mark of specimen | R.S. |

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/samples marked R.S. has/have been taken in my presence which represent 20 cum quantity of works/supply made at site/store

Signature of JE — Signature of Contractor (Rajkumar Sharma) — Signature of Officer taking sample (EE/AE)

Part II

TEST REPORT

No. SE(QC)/AE(Lab.)/2017-18/D-417 Date: 20/06/18
Test No. 361 Date: 18-6-18
Date of Receipt 18/6/18
Date of testing 18/6/18
Concrete Mix Days test 28 days

| S. No. | Wt. of specimen in gms | Area in sq.cm. mm² | Compressive strength Load (Ton) KN | Comp. strength (Kg/sq.cm) N/mm² | Average Strength (Kg/sq.cm) N/mm² | Remarks |
|---|---|---|---|---|---|---|
| 1 | 8414 gm | 22500 | 671 KN | 29.82 | 30.06 N/mm² | EE May Accept the Accordingly |
| 2 | 8498 " | 22500 | 676 KN | 30.04 | | |
| 3 | 8526 " | 22500 | 682 " | 30.31 | | |

Tested in my presence

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

COPY TO:
1. EE/C-8
2. O/C

18/6/18
Assistant Engineer (QC)
DUSIB, Vikas Kutir, ITO
Assistant Engineer (QC)
Delhi Urban Shelter Improvement Board
Govt. of N.C.T. of Delhi
ITO, New Delhi-02