

To

The Assistant Engineer (QC)
Quality Control Lab., DUSIB
Vikas Kutir, ITO, New Delhi

R.NO: 0554
RECEIVED 05 JUN 2017

Part I

Dispatch No. 01228/EE C-5/DUSIB/13/20/2-18
Sub: Testing of Bricks/Brick tiles for Compressive Strength/Dimension.

Date: 05/06/17

I.D.


AL-10/WH/4945/EE C-5/DUSIB/2017-18 /D- 130 dt. 16.05.2017


Name of work: Construction of BVK/C HALL


S. H. : Renovation of BVK (used as Community Hall) at JJ Basti Khizarhaba (Batla House) Okhla (AC-5

1. Details from where sample is collected -----site-----
2. Name of Circle/Division -----Circle-II/C-5-----
3. Name of Junior Engineer -----Sh. Sunder Kumar-----
4. Name of Assistant Engineer -----Sh. K.M. Goel-----
5. Name of Executive Engineer -----Sh. S.K. Varshney-----
6. Name of Contractor/Agency -----Sh. Y.K. Goyal-----
7. Name of Officer collecting sample: -----Sh. K.M. Goel-----
8. Name of Officer collecting sample: -----AE/JE-----
9. Date of collection/Date of filling frog: -----21.5.17/01.06.17-----
10. Date of testing: -----05/06/17-----
11. Identification Mark: -----V.K.M-----
12. Class designation: -----7.5-----
13. No. of specimen sent for testing: -----5 Nos-----

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/samples marked-----has/have been taken in my presence which represent 10.000 quantity of works/supply made at site/store.


Signature of JE
Incharge of work


Signature of Contractor


Signature of Officer
taking sample (EE/AE)

Part II

TEST REPORT

No. SE (QC)/AE (Lab.)/2017/D-

Date:


Test No. 0554 Date: 5.6.17

Date of Receipt: 5.6.17

Date of Testing: 5.6.17

(A) COMPRESSIVE STRENGTH

S. No	Dimensions			Maximum Strength. Failure (T)	Compressive Strength Failure (kg/sq.cm)	Av. Comp. Strength. Kg/sq.cm
	Length (cms)	Width (cms)	Area (sq.cm)			
1.	22.00 x	10.70	=	22.00	93.45	90.46
2.	22.50 x	10.60	=	21.00	88.05	
3.	22.00 x	10.60	=	21.00	90.05	
4.	22.00 x	10.50	=	20.00	86.58	
5.	22.20 x	11.00	=	23.00	94.18	


Tested in my presence


(B) DIMENSION TEST FOR 20 BRICKS

1. Length :
2. Width : NOT ASKED FOR
3. Height :

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

Copy to:-

1. EE/C-5
- 2.


Assistant Engineer (QC-Lab)
DUSIB, Vikas Kutir, ITO
Assistant Engineer (QC)
Delhi Urban Street Improvement Board
Govt. of Delhi
ITO, New Delhi-02