The Assistant Engineer (QC) Quality Control Lab., DUSIB Vikas Kutir, ITO, New Delhi RECEIVED 2 4 MAY 2017

Part I Dispatch No. D -19 Sub: Testing of Bricks for Water Absorption / Efflorescence Date: 24/5/17

A.L. No. WI/60311/109/PG/EE C-7/2016-17/D-227, dated: 17/02/2017.

1. Name of work: Refurbishment of Night Shelter under NULM. SH Refurbishment of Night Shelter under NULM at Hall No. 4, Fatehpuri, Near Old Delhi Railway Station.

2. Details from where sample is collected Site at above work 3. Name of Circle / Division: 3 / C-7 4. Name of Junior Assistant Dinesh Kr. Tyagi 5. Name of Assistant Engineer: Sh. K.L. Maurya Sh. K.B. Sharma 6. Name of Executive Engineer: 7. Name of Contractor / Agency: Sh. Y.K. Goyal 8. Name of Officer collecting sample: Sh. K.L. Maurya 24-05-17

9. Date of collection 10. Date of testing:

11. Identification Mark:

12. Class designation:

13. No. of specimen sent for testing:

7.5 DHK

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample /samples marked DH | has/have been taken in my presence which represent guantity of works/supply made at site/store.

Signature of Contractor

Signature of Off

Part II

TEST REPORT

No. SE (QC) /AE (Lab.) / 2016-17/ D-

Test No. 0468

Date: 24.517

Date of Receipt: 24.5.1)

Date:

(A). WATER ABSORPTION

Date of testing up to: 30,5.17

S.No.	Dry: Wt. (gms)	Wet. Wt. (gms)	Water Absorbed (gms)	% age water absorbed	Average water absorption
1.	2953	3302	349	11,82	ACCEPTABL
2.	2962	3309	347	11,71	
3.	2863	3188	325	11,35	
4.	3094	3425	331	10,70	
5.	2861	3186	325	11,35	

(B) EFFLORSESCENCE:

ACCEPTABLEDate of testing up to: 13.6.17

Efflorescence found: Nil / Slight/ Moderate / Heavy

Only testing has been conducted in this laboratory. The sample/samples has/have been collected are handed over by field staff of the concerned division.

Copy to:-

1. EE/C-7

010

Assistant Engineer (QC-Lab) DUSIB Vikas Kettir (00) Delhi Urban Sneller Improvement Board 30VI. of S.C.T. of Delhi

ITC., New Delni-02