

The Assistant Engineer (QC)  
Quality Control Lab., DUSIB  
Vikas Kutir, ITO, New Delhi

R.No. 891  
RECEIVED 25 JUL 2017

**Part I**

Dispatch No. AB-5/C-12/DUSIB/2017/D-87 Date: 24/07/17

**Sub: Testing of Bricks/Brick tiles for Compressive Strength/Dimension.**

AL No. 19/WK/7205(175)/EEC-12/DUSIB/2017-18/D-482 dated 13.06.2017

NOW: GIA to DUSIB for existing infrastructure SH: Construction of boundary wall for open land earmarked for JSC in block-B near plot no. 2571 etc. at SRS Holambi Kalan Ph-II (Metro Vihar).

(Project ID 000008604).

1. Details from where sample is collected
2. Name of Circle/Division
3. Name of Junior Engineer
4. Name of Assistant Engineer
5. Name of Executive Engineer
6. Name of Contractor/Agency
7. Name of Officer collecting sample:
8. Date of collection/Date of filling frog:
9. Date of testing:
10. Identification Mark:
11. Class designation:
12. No. of specimen sent for testing:

Site  
Circle-4/C-12  
Rakesh Kumar  
Sh Kamal Singh  
M/s Y.K. Goel  
Rakesh Kumar/Kamal Singh  
20-07-2017  
25-07-2017  
ABYA  
75  
5 X 8

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/samples marked ABYA has/have been taken in my presence which represent-----quantity of works/supply made at site/store.

Signature of AE  
Incharge of work

Signature of Contractor

Signature of Officer  
taking sample (EE/AE)

**Part II**

No. SE (QC)/AE (Lab.)/2017-18/D- 1026

Test No. 891 Date: 25/7/2017

Date of Receipt: 25/7/2017

Date of Testing: 25/7/2017

**(A) COMPRESSIVE STRENGTH**

S. No	Dimensions			Maximum Strength. Failure (T)	Compressive Strength Failure (kg/sq.cm)	Av. Comp. Strength. Kg/sq.cm
	Length (cms)	Width (cms)	Area (sq.cm)			
1.	22.60	10.50	237.30	22.50 T	94.82	89.75 kg/cm <sup>2</sup>
2.	22.70	10.90	247.43	24.00 T	96.99	
3.	22.40	11.00	246.40	25.00 T	101.46/100	
4.	22.20	10.50	233.10	19.00 T	81.51	
5.	22.30	10.70	238.61	18.00 T	75.44	

Tested in my presence

**(B) DIMENSION TEST FOR 20 BRICKS**

1. Length :
2. Width :
3. Height :

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

Assistant Engineer (QC-Lab)

DUSIB, Vikas Kutir, ITO

Delhi Urban Shelter Improvement Board  
Govt. of N.C.T. of Delhi