The Assistant Engineer-QC Quality Control, DUSIB Vikas Kutir, ITO, New Delhi RECEIVED 1 3 NOV 2017

Part I

Dispatch No AE-V/C-1/DUSIB/2017-18/D- 66

Date: 13/11/12

Sub: Testing of CC cubes of mix - for 7/28 days Compressive Strength.

A. L. No. WA/4222/AL-49/EE C-1/2016-17/D-1276

1. Name of Work: National Urban Livelihood Mission(NULM) Sub Head: Construction of Shelter for Urban Homeless at Sector-3, Ph-III, Dwarka (Project ID-8632)

2.	Details from where sample is collected	From Site
_		0: 1 4/04

3. Name of Circle/Division: --Circle-1/ C-1-----

4. Name of Junior Engineer: -----V S Verma-----5. Name of Assistant Engineer:

-----P K Singh-----6. Name of Executive Engineer:

----- M/s Pushpa Builders -----7. Name of Contractor/Agency:

8. Name of Officer collecting sample: -----VS Verma 9. Date of collection: -----16.10.2017-

13.11.2017 10. Date of testing:

-----M-25-----11. Required strength:

12. No. of specimen sent for testing: -----3----------15x15x15cm-----13. Size of specimen:

-----M-----14. Mark of specimen:

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/ samples marked-- M -- has/have been taken in my presence which represent 25 cum quantity of works/supply made at site/store.

Signature of JE/AE' In charge of work

Signature of Contractor

Signature of Officer

taking sample (EE/AE)

TEST REPORT

No. SE(QC)/AE(QC)/2015-16 /D- 2092

Test No. 1782 Date: 13/11/17

Da*t'e of Receipt: 13/11/2017
Date of testing: 13/11/2017

S. No	Wt. of specimen Area in		Compressive Strength		Average Strength	Remarks
	in gms	sq.cm.	Load	Comp. strength	(Kg./sq.cm)	
			(Tonnes)	(Kg./sq.cm)		
1.	8473	285	61.507	273.33		
2.	8794	ns	63.507	282.22	280.74	
3.	8760	Sur	F 02.43	286.67	Kelun	

Only testing has been conducted in uns laborated and the concerned division. Only testing has been conducted in this laboratory. The sample/samples has/have been collected and

Assistant Engineer, QC DUSIB, Vikas Kutir, ITO