0 6 MAR 2019

pNO:2013

Part I

Dispatch No AE-IV/C-1/DUSIB/2018-19/D- 2 36

Date: 6/3/19

Sub: Testing of CC cubes of mix ------M-25 ----- for 7/28 days Compressive Strength.

A. L. No. WA/4222/AL-49/EE C-1/2016-17/D-1276

Dated: 02.03.2017

1. Name of Work: National Urban Livelihood Mission(NULM)

Sub Head: Construction of Shelter for Urban Homeless at Sector-3, Ph-III, Dwarka (Project ID-8632)

2.	Details from where sample is collected	From Site
3.	Name of Circle/Division:	Circle-1/ C-1
4.	Name of Junior Engineer:	Mohit
5.	Name of Assistant Engineer:	V S Verma
6.	Name of Executive Engineer:	I K Srivastva
7.	Name of Contractor/Agency:	M/s Pushpa Builders
8.	Name of Officer collecting sample:	V S Verma
9.	Date of collection:	06-02-2019
10.	Date of testing:	06-03-2019
11.	Required strength:	M-25
12.	No. of specimen sent for testing:	3
13.	Size of specimen:	15x15x15cm

14. Mark of specimen: Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/ samples marked-----has/have been taken in my presence which represent----cum quantity of works/supply made at site/store.

Signature of JE/AE

Signature of Contractor

Signature of Officer

In charge of work

taking sample (EE/AE)

TEST REPORT

No. SE(QC)/AE(QC)/2012-18/D-2353

Date: 11 03 14.
Date: 6.3 9

Test No. 2013

Date of Receipt: 6.3.19 Date of testing: 06.3.19

S. No	Wt. of specimen Area in		Compressive Strength		Average Strength	Remarks	
	in gms	sq.cm,	Load (N) lan	Comp. str (N/sq.mm)	rength	(N/sq.mm)	
1.	8394 gm	mo	650	28.89			EE May
2.	8455-4	ma	979	29:16	28.9.	C	cordingly
3.	8479 0	mw	648	28-80	H	lun-	

Tested in my presence

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

COPY TO IEE/C-1 2 0/c

Assistant Engineer (QC) Delhi Urban Sheller Improvement Board BOYL OF 4.C.T. of DoIN! ITC, New Delhi-02