28 MAY 3918

The Assistant Engineer(QC)
Quality Control Lab., DUSIB
Vikas Kutir, ITO, New Delhi

Part I
Dispatch No

Date: Date

## A. L. No. 60/WJ-6981/(27)/EE/C-6/AE-V/2017-18/D-1145 Dt.:15.11.2017

1. Name of work: EIUS.

SH: Providing and laying CC pavement in the deteriorated approach of JJ Basti Dr. Ambedkar camp, Mehrauli (Chattarpur Pahari).(ID- 8986)

- 2. Details from where sample is collected From the Site of work-----
- 3. Name of Circle/Division Circle II/C-6 -----
- 4. Name of Junior Engineer Sh. Bhupender Kumar-----
- 5. Name of Assistant Engineer Sh. Lal Chand-----
- 6. Name of Executive Engineer Sh. O.P. Pruthi
- 7. Name of Contractor/Agency M/s Lucky
- 8. Name of Officer collecting sample: Sh. Lal Chand -----
- 9. Date of collection: 29-4-2018
- 10. Date of testing: 27-5-2018

  11. Required strength: As per CPWD Specification ----250 Kg/sam-

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/samples marked-----has/have been taken in my presence which represent 30 m3 approx quantity of works/supply made at site/store.

Signature of AE In charge of work

Signature of Contractor

Signature of Officer taking sample (AE/EE)

Date: 28/05/18

Part II

TEST REPORT

No. SE(QC)/AE(Lab.)/2014-18/D- 318

Test No. 290 Date: 28.5.18

Date of Receipt: 28518
Date of testing: 28518

Concrete Mix: 7518

Days test: 29 do

Concre		$m \cdot 20$		Da	ys lest: 29 days	
S. No	Wt. of specimen	Area in	Compressive Strength		Average Strength	Remarks
	in gms	sq.cm.	Load LAN	Comp. strength	(K.g./sq.cm)	
		mmt	(Tonnes)	(Keg./sq.cm) NI	m2 NImz	
1.	8 484 gm	28500	288 MH	26.137	EE	May
2.	क्ष १६०	2200	v 082	25.78	25.8 ACCO	ding
3.	85024	375W	276 "	32.60	Num2	
(gad*)100					*	

REPUK!

Tested in my presence

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

Assistant Engineer (QC-Lab)

DUSIB, Vikas Kutir, ITO