

DELHI URBAN SHELTER IMPROVEMENT BOARD
GOVT. OF NCT OF DELHI
OFFICE OF THE EXECUTIVE ENGINEER-C-8

RNO. 275

24 MAY 2018

To

The Assistant Engineer (QC)
 Quality Control Lab., DUSIB
 VikasKutir, ITO, New Delhi.

3350

Part I

Dispatch No. D-23/AC-4/C8/DUSIB/18

Date: 24/5/18

Sub: Testing of Bricks/Brick tiles for Compressive Strength/Dimension.

A. L. No: 65/LOC/EEC-8/DUSIB/2017-18/D-1130 dt. 18-3-2018

1. Name of work: C/O C. Hall / DM.

SH: A/R & M/O special repair of existing B.V.H. of A-block
Gokal Puri (ID 000009819)

2. Details from where sample is collected
3. Name of Circle/Division
4. Name of Junior Engineer
5. Name of Assistant Engineer
6. Name of Executive Engineer
7. Name of Contractor/Agency
8. Name of Officer collecting sample
9. Date of collection/date of filling frog:
10. Date of testing:
11. Identification Mark:
12. Class Designation:
13. No of specimen sent for testing:

From site

Circle III/C-8

Sh. Ashok Bhaskar

Sh. Anil Kumar

Sh. R. B. Sharma

M/s. Bharat Associates

Sh. Anil Kumar

18-5-2018

23-5-2018

MBF

CD-75

20 Nos.

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/samples marked--MBF--has/have been taken in my presence which represent--20--quantity of works/supply made at site/store.

Signature of JE
 In charge of work

Signature of Contractor

Signature of Officer
 taking sample (EE/AE)

Part II

TEST REPORT -

No. SE (QC)/AE (Lab.)/2017-18/D- 305

Test No. 275 Date: 24.5.18

Date: 25/05/18

Date of Receipt: 24/5/18

Date of Testing: 24/5/18

(A) COMPRESSIVE STRENGTH MBF

S. No	Dimensions			Maximum Strength. Failure (T)	Compressive Strength Failure (kg/sq.cm)	Av. Comp. Strength. Kg/sq.cm
	Length (cms)	Width (cms)	Area (sq.cm)			
1.	22.40	10.60	237.44	20.07	84.23	ACCEPTABLE 91.64 kg/cm ²
2.	22.20	11.10	246.42	24.07	97.39	
3.	22.20	11.10	244.20	22.07	90.09	
4.	22.40	10.80	241.92	26.07	107.47/100	
5.	22.20	11.20	248.64	21.50 T	86.47	

Tested in my presence

(B) DIMENSION TEST FOR 20 BRICKS

1. Length :
2. Width :
3. Height :

Only testing has been conducted in this laboratory. The sample/samples has/have been Collected and handed over by the field staff of the concerned division.

Copy to:-

1. BE/C-8
2. O/C

Assistant Engineer (QC-Lab)
 DUSIB, Vikas Kutir, ITO

Assistant Engineer (QC)
 Delhi Urban Shelter Improvement Board
 Govt. of N.C.T. of Delhi
 ITO, New Delhi-02