

RECEIVED 16 FEB 2017

Part I

No. AL-07/28/AB-II/c-1/D

15/2/17 Date 18.5.16

Sub: Testing of Bricks / Bricks Tiles for Water Absorption / Efflorescence

AL No WA/4222/AL-7/EEC-1/2016-17/D 370 DL 18.5.16

1. Name of work: Environmental Improvement in Urban Slum (E.J.U.S)

Sub Head: Providing and cement concrete flooring and const. of Drain in the lane of JS cluster Indira camp No. 5 Vikashpuri

2. Details from where sample is collected: At Site
3. Name of Circle / Division: C-1
4. Name of Junior Engineer: T.P. Thakur
5. Name of Assistant Engineer: AK Nisha
6. Name of Executive Engineer: Sh. P.K. Singh
7. Name of Contractor / Agency: M/s. Durga const. Co.
8. Name of Officer Collecting Sample: AK Nisha
9. Date of collection / Date of filling frog: 17.2.17
10. Date of testing: 15.2.17
11. Identification Mark: ARH
12. Class Designation: 25
13. No. of specimen sent for testing: 10 Nos.

Specimen relating to work mentioned above is / are sent for testing. It is certified that the sample (s) marked .....has / have been taken in my presence which represent ..... quantity of work / supply made at site / store.

Signature of J.E.

Signature of Contractor

Signature of Officer Taking sample (EE / AE)

Part II

No. SE(QC)/AE(Lab)/2007/D-4605

Test No. 2365 Date 16.2.17

(A) WATER ABSORPTION

Date 10/02/17

Date of Receipt 16.2.17

Date of testing up to 21.2.17

S. No.	Dry Weight (Grams)	Wet Weight (Grams)	Water Absorbed (Grams)	% age Water Absorbed	Average Water Absorption
1.	2875	3297	422	14.68	13.68% ACCEPTABLE
2.	2979	3420	441	14.80	
3.	3042	3416	374	12.29	
4.	3050	3475	425	13.93	
5.	3110	3505	395	12.70	

(B) EFFLORESCENCE

ACCEPTABLE

Date of testing upto 2.3.17

Efflorescence found: Nil / Slight / Moderate / Heavy

Only testing has been conducted in this laboratory, the sample have been collected, cured and handed over by the field staff of the division.

COPY TO  
1. EEC-1  
2. OK